

OPERATING MANUAL

525N - 90

SINGLE-MODE OPTICAL LOSS TEST SET



fiberTOOLS™

97-0525-90, Rev. B

 **Tempo**[®]
A Textron Company

TEMPO - 525-90 OLTS OPERATING MANUAL

CUSTOMER TRAINING & TECHNICAL SUPPORT

Copyright © 2005

Tempo - a Textron Company. All rights reserved.

Tempo Research, a Delaware Corporation

Statement of Warranty

Tempo warrants this product to be free from defects in materials and workmanship for a period of one (1) year from the date of shipment. During the warranty period we will, at our option, either repair or replace any product that proves to be defective. To exercise this warranty, write or call your local Tempo representative, or contact Tempo directly. You will be given prompt assistance and return instructions. Send the instrument, transportation prepaid, to the indicated service facility. Repairs will be made and the instrument will be returned transportation prepaid. Repaired products are warranted for the balance of the original warranty period, or at least ninety (90) days.

Year 2000 Compliance:

Tempo warrants that the 525 and its ReportWriter Software are designed to be used after the calendar year 2000 A.D., and that the Software will operate without error relating to date data, specifically including any error relating to, or the product of, date data which represents or references different centuries or more than one century.

Limitations of Warranty

This warranty does not apply to defects resulting from unauthorized modification or misuse of any product or part. This warranty also does not apply to AC adapters, batteries, or damage from battery leakage.

This warranty is in lieu of all other warranties, expressed or implied, including any implied warranty of merchantability or fitness for a particular use. Tempo shall not be liable for any indirect, special, or consequential damages.

TABLE OF CONTENTS**Section 1 - GENERAL INFORMATION****PAGE: 1**

Product Description	1
Safety Terms & Precautions	2
Laser Safety	3
Unpacking & Inspection	3
Reporting Shipping Damage, Service & Product Ordering	4
Preparation for Use	5-12

Section 2 - QUICK START GUIDE**PAGE: 13**

Front Panel Controls & Connectors	13
Powerup & Setup Functions	14-15
Establish Measurement Reference – Side-by-Side & Loopback	16-17
Running an IL/RL AutoTest – 1310/1490/1550nm	18-20

Section 3 - SCREEN FUNCTIONS & DESCRIPTIONS**PAGE: 21**

Autotest Main Screen	21
Reference Methods Screens	22
Setup Screens	23-25
Menu Screen	26
View Data Screens	27-28
Tools Screens	29-30
OPM/Source	31-32
Return Loss	33-34
Send Message	35

Section 4 - SPECIFICATIONS**PAGE: 37**

Optical Power Meter Specifications	37
Specification Summary of Lasers	38
AutoTest Specifications	38
Return Loss Specifications	38
Mechanical Specifications	38
Parts & Accessories	39
Technical Support & Service	40
Periodic Calibration	40



Product Description

The 525-90 bi-directional optical test set is a compact handheld instrument incorporating an IL/RL AutoTest feature, Optical Power Meter and Return Loss Meter. The 525 is fitted with an APC Universal Connector Interface on the laser source, and a Snap-On Connector on the power meter, permitting the unit to be used with compatible connectors.

All models in the series incorporate features that make fiber optic tests and measurements more efficient and convenient:

- * Built-in laser sources simplify test and measurement
- * Non-volatile data storage for more than 1,000 measurements
- * Pass/Fail testing mode
- * RS232 interface for report printing, remote testing, data uploads/downloads
- * Multiple power options, including rechargeable nickelmetal hydride (NiMH) batteries, alkaline batteries, concurrent AC/battery trickle charge mode, and AC-only operation

A large, backlit LCD display enables users to easily view measured optical power levels and the calibration wavelength in use. Intuitive controls make measurements, data storage and retrieval, and report printing easy and convenient.

A pair of identical 525 test sets are required in order to perform automated bi-directional testing and data exchange between the instruments. Once a side by side or loopback measurement reference has been established either unit can initiate the AutoTest. The unit initiating the test becomes the master or local test set (designated 'A' in the data results screens), the other unit becomes the slave or remote unit (designated 'B' in the data results screens). Used as a pair, the 525 also has eight stored messages that can be sent between units offering the ability for technicians to communicate with each other while performing measurement tests.

525-90 PON Single-Mode Optical Test Sets

The 525-90 optical test sets can perform optical power measurements within a range of +10dBm to -65dBm. They are calibrated at: 850nm, 980nm, 1310nm, 1490nm, 1550nm and 1625nm. There are Laser sources available in the unit at 1310nm, 1490nm and 1550nm.

Safety Terms in This Manual

A **WARNING** identifies dangers that could result in personal injury or death.

A **CAUTION** identifies hazards that could damage the instrument.

A **NOTE** is followed by information that may be beneficial during the use of the instrument.

Specific Precautions

Never use the instrument with a battery charger, rechargeable battery pack, or external power supply not expressly approved by Tempo.

Do not insert any batteries with the polarity reversed. Do not mix batteries of different manufacturers or types, e.g., alkaline and non-alkaline.

The instrument battery cover should only be opened to change the batteries, or to install or remove a rechargeable battery pack, in accordance with the procedures in this manual. No user-serviceable parts are inside.

Avoid leaving the instrument in direct sunlight, or near direct sources of heat.

Always replace the interface dust caps when the instrument is not in use. Store the instrument and interface adapters in a cool, dry, and clean place.

Protect the instrument from strong impacts or shock.


While splashproof, the instrument must not be immersed in water or stored in areas with high humidity.

When necessary, the case, front panel, and rubber cover should only be cleaned using a damp cloth. Do not use abrasives, harsh chemicals, or solvents.

Continued on the next page...

Laser Safety

The 525 Series optical test sets are laser devices conforming to the requirements of CDRH, CFR 1040, Subchapter J. While there is no potential for eye damage due to unaided direct exposure, users should always avoid looking directly into the output port. The use of optical viewing instruments (such as microscopes, magnifiers, etc.) should always be avoided. The use of these devices around active fibers can focus a highly intense beam of energy onto the retina of the eye, which can result in permanent damage or blindness.



Unpacking and Inspection

The 525 Series optical test set has been carefully inspected before shipment. When received, the shipping carton should contain the items listed below:

- 525-90
- AC Adapter
- RS232 Cable
- Connector Cleaning System (All-In-One)
- Adapter Cleaning Wands
- SOC Adapter (ST, SC or FC available per customer request)
- Ceramic UCI Adapter (ST, SC or FC available per customer request)
- SOC Puller Tool
- Mandrel (for SM units only)
- CD—Containing User Manual, ReportWriter Software, ReportWriter Manual, 525-90 Operating Manual

Please account for and inspect each item while unpacking and preparing the instrument for use.

If the instrument received is damaged, write or call Tempo in accordance with the instructions below.

Keep the shipping carton in case reshipment is required for any reason, e.g., annual recalibration.

Continued on the next page...

Reporting Shipping Damage

All instruments are shipped FCA Vista, Calif., when ordered from Tempo.

If you receive a damaged instrument, you should:

1. Report the damage to your shipper immediately.
2. Save all shipping cartons.
3. Inform Tempo and follow the instructions given by customer service. You will be issued a Returned Materials Authorization (RMA) number if the instrument must be shipped back to Tempo.

To contact Tempo customer service, call (800) 642-2155 from 7 a.m. to 4:30 p.m. Pacific time.

Inquiries may also be faxed to Tempo at (760) 598-5634, or sent via e-mail to fiberoptics@tempo.textron.com.

Failure to follow this procedure may affect your claim for compensation.

Service and Product Ordering

For warranty or non-warranty service, please Telephone, Fax or E-Mail Tempo at -

TEL: 1 800 642-2155 or 1 760 598-8900
FAX: 1 760 598-5634
E-MAIL: REPAIR@TEMPO.TEXTRON.COM

For product and ordering information, please Telephone, Fax or E-Mail Tempo at -

TEL: 1 800 642-2155 or 1 760 598-8900
FAX: 1 760 598-5634
E-Mail: SALES@TEMPO.TEXTRON.COM
WEB: WWW.TEMPO.TEXTRON.COM

Preparation for Use

Charging the NiMH Battery Pack

The 525 Series optical test set is shipped with a nickel-metal hydride (NiMH) battery pack installed. This battery pack must be charged before the instrument is used for the first time.

To charge the NiMH battery pack, do the following:

1. Plug the power transformer/NiMH battery charger into a wall outlet.
2. Insert the plug from the power transformer/NiMH battery charger into the DC input receptacle on the side of the instrument.
3. The red charge state indicator will illuminate. Allow the batteries to charge until the indicator turns off (4 hours maximum).
4. Disconnect the unit from the power transformer/NiMH battery charger.

The instrument can now be used.

NOTE: The NiMH battery pack and power transformer/NiMH battery charger will become warm during use. This is normal.

Trickle Charge Function

The 525 Series optical test set incorporates a trickle charge function that prevents the batteries from being damaged from overcharging. The instrument can remain connected to the power transformer/NiMH battery charger indefinitely without damaging the batteries.

The trickle charge function monitors the condition of the batteries when the instrument is connected to the power transformer/NiMH battery charger. If the batteries are drained, the instrument will begin a maintenance charge cycle to ensure they are at full capacity.

Setting the Internal Clock and Calendar

The 525 Series optical test set incorporates an internal clock and calendar, permitting the time and date to be recorded when a measurement is saved.

The internal clock and calendar should be set before using the instrument for the first time using the Set 525 Clock feature in the Utilities mode of the ReportWriter software.

Continued on the next page...

Boot, Housing and Power Options

Removing/Installing the Rubber Boot

The 525 Series optical test set is fitted with a rubber boot that provides impact and shock protection during use. This rubber boot incorporates a swing-out stand, permitting convenient viewing of the display when the instrument is used on the benchtop.

The rubber boot must be removed to access the battery compartment cover on the back of the instrument housing. To remove the boot, do the following:

1. Grasp the boot in both hands and gently peel back the sides starting from the top.
2. Press the back of the instrument through the rectangular hole in the boot to pivot it forward.
3. Pull the instrument away from the boot.

Installation of the boot is the reverse of removal. Make sure the instrument is seated snugly in the boot before use.

NOTE: To prevent damage from shock or impact, do not use the instrument without the boot in place.

Removing/Installing the Battery Cover

The battery compartment is sealed by a plastic cover secured by two Phillips screws, which must be removed for access. To open the battery compartment, do the following:

1. Remove the rubber boot as described in the preceding section.
2. Lay the instrument display-side down on a soft surface, such as a towel, to prevent scratching of the front panel.
3. The two screws securing the battery cover will now be visible. Remove both screws by turning them counterclockwise using a #1 Phillips screwdriver. Put the screws in a safe place.
4. The battery cover can now be lifted away from the instrument housing. Gently pry up on the bottom of the cover. **DO NOT USE A METAL TOOL TO PRY OPEN THE COVER.**



Installation of the battery cover is the reverse of removal. Take care not to overtighten the screws securing the battery cover or damage may result.

Continued on the next page...

Multiple Power Options

The 525 Series optical test set features four power options:

1. Rechargeable nickel-metal hydride battery operation. Nickel-metal hydride battery pack required.
2. Concurrent nickel-metal hydride (NiMH) battery recharging (trickle charging) and AC operation.
3. Alkaline battery operation. Four AA-type alkaline batteries required.
4. AC-only operation.

CAUTION: Never use the instrument with a battery charger, rechargeable battery pack, or external power supply not expressly approved by Tempo.

Rechargeable NiMH Battery Operation

The 525 Series optical test set is shipped with a rechargeable nickel-metal hydride (NiMH) battery pack installed. The battery can be trickle-charged while the instrument is in use.

The nickel-metal hydride battery pack provides up to 10 hours of continuous operation.

NOTE: The nickel-metal hydride battery pack incorporates a device that enables the charging circuit to function. The 525 Series optical test set must only be used with NiMH battery packs with this part number. Other battery packs will not charge when installed in the instrument.

CAUTION: Do not remove the plastic covering from the battery pack.

Continued on the next page...

Alkaline Battery Operation

For convenient field service, four (4) AA-type alkaline batteries may be used to power the 525 Series optical test set after the nickel-metal hydride battery pack has been removed. Alkaline batteries will provide up to 24 hours of continuous operation.

NOTE: The instrument will not charge alkaline batteries when the power transformer/NiMH battery charger is connected. This allows the instrument to be operated using AC power when alkaline batteries are installed.

To use alkaline batteries, do the following:

1. Remove the battery compartment cover.
2. Remove the nickel-metal hydride battery pack.
3. Install four AA-type alkaline batteries as shown inside the battery compartment. Do not reverse the polarity of the batteries.
4. Replace the battery compartment cover.

AC-Only Operation


The 525 Series optical test set may be used without any batteries installed. To do so, connect the power transformer/NiMH battery charger to the instrument, and plug the other end into an AC power outlet.

LED Indicators, DC Input, and RS232 Port

The DC input receptacle and RS232 port are located on the right side of the instrument when viewed from the front. If the protective rubber boot is installed, lift the flap for access.

1. Source active indicator: This indicator, located on top of the unit between the input and output interfaces, will illuminate when the laser source is switched on. The indicator will go out when the source is switched off.
2. Modular RS232 port: Stored data can also be displayed on-screen using ReportWriter software, Microsoft HyperTerminal, or other serial communications applications.
3. Charge state indicator: This indicator will illuminate when the nickelmetal hydride (NiMH) battery pack is fast-charging using the power transformer / NiMH battery charger. The charge state indicator will go out when the battery is fully charged and the instrument enters trickle charge mode.

NOTE: The charge state indicator does not function for alkaline battery operation, or if the batteries are removed.



4. DC input receptacle: The power transformer/NiMH battery charger is connected to this receptacle.

CAUTION: Never use the instrument with a battery charger, rechargeable battery pack, or external power supply not expressly approved by Tempo.

Snap-On Connector (SOC) Interface

The optical power meter input of the 525 Series optical test set incorporates a Snap-On Connector (SOC) interface and is used with standard Tempo 10-series SOC adapters. SOC interfaces and adapters offer superior repeatability and are compatible with most industry standard fiber optic connectors. SOC adapters can also be quickly removed from the interface to permit cleaning of the detector window in accordance with the following instructions.

Removing an SOC Adapter →

1. Grasp the sides of the SOC adapter and pull it off the interface. SOC adapters require considerable force to remove. Do not attempt to pry the adapter off the interface or damage will result.
2. Put the adapter in a clean place.



Installing an SOC Adapter →

1. Locate the anti-rotation key on the interface.
2. With the keyway properly aligned, push the adapter over the interface until it snaps in place.



Universal Connector Interface (UCI)

The laser source output of the 525 Series optical test set incorporates a physical contact Universal Connector Interface (UCI-PC) and is used with standard Ceramic UCI adapters. UCI adapters are available for most industry standard fiber optic connectors.

Removing a UCI Adapter →

1. Turn the knurled adapter shell counter-clockwise until it is free from the interface.
2. Pull the adapter off the ferrule.
3. Put the adapter in a clean place.



Installing a UCI Adapter →

1. Press the adapter firmly over the interface ferrule until it reaches the stop.
2. Rotate the adapter body until the anti-rotation key engages.
3. Firmly tighten the knurled adapter shell by turning it clockwise.



Cleaning the Instrument Interfaces

To ensure absolute measurement integrity, it is essential that all instrument interfaces are cleaned before each use. Tempo recommends using a lint-free cloth, such as Texwipe TX404, and reagent-grade isopropyl alcohol to clean the SOC and UCI interfaces of the 525 optical test set.

NOTE: It is essential that the connectors and interfaces to be mated are cleaned each and every time before connecting or re-connecting them to anything—instrument inputs/outputs, transmission equipment, patch panels, etc.

To clean the interfaces, do the following:

1. Remove the SOC or UCI adapter in accordance with the preceding instructions.
2. Wipe once across the interface with a clean lint-free cloth, such as Texwipe TX404. When cleaning a SOC interface, take care not to press too firmly to avoid breaking the detector window.

NOTE: If the interface is extremely dirty, reagent-grade isopropyl alcohol will be required to clean it. Moisten the lint-free cloth with alcohol and wipe once across the interface. Make sure all residual alcohol has completely evaporated before proceeding to the next step.

3. Re-install the SOC or UCI adapter in accordance with the preceding instructions.

Cleaning a UCI Adapter

For increased durability, most UCI adapters incorporate a ceramic alignment sleeve that must be cleaned every time before a connector is mated. Failure to clean the sleeve prior to mating a connector will result in endface contamination and inaccurate measurements.

NOTE: UCI adapters incorporating a ceramic sleeve do not require frequent cleaning. Such adapters must be handled carefully to avoid sleeve breakage.

To clean a UCI adapter, do the following:

1. Remove the adapter from the interface.
2. Insert a new cleaning wand into the through-hole of the adapter until it stops.
3. Twist the wand, remove it and discard. Do not reuse the cleaning wand.




Cleaning Fiber Optic Connectors

To ensure absolute measurement accuracy and repeatability, fiber optic connectors must always be cleaned before conducting a fiber optic measurement. Dust and oil contamination on the connector end-faces, as shown at right, can result in abnormally high insertion loss readings and other anomalies.


Tempo recommends the use of the All-In-One cleaning tool for fiber optic connectors in accordance with the enclosed instructions. If an All-In-One cleaning tool is not available, the connectors should be cleaned as follows:

1. Moisten a clean, lint-free cloth, such as Texwipe TX404, with reagentgrade isopropyl alcohol.
2. Wipe once across the connector endface with the damp part of the cloth using moderate pressure. Make sure the alcohol has completely evaporated before commencing.
3. If possible, visually inspect the connector endface using a magnifier or microscope, such as a Leica 200x FiberVue microscope, Tempo Part No. FVK-200/U25. If the end face still appears dirty, clean it again.



WARNING: Never clean or visually inspect a fiber optic connector under power. Viewing the end of an optical fiber under power can cause permanent eye damage or blindness.

Front Panel Controls & Connectors




AUTOTEST QUICK START GUIDE

THIS IS A QUICK START REFERENCE ONLY. Refer to additional manual sections for detailed descriptions of how to configure and perform testing with the 525-90 Single-Mode OLTS.

REMEMBER: To ensure absolute measurement accuracy, connectors must always be cleaned before conducting a fiber optic measurement.

Power Up and Setup - Test Type, Wavelength, Auto Save & Threshold

1. Press the Power Button. The startup logo and version will display briefly, followed by the AutoTest Main Screen.
2. To select the Test Type, Wavelength(s), Data Save Mode and Threshold settings required, press SETUP softkey.




3. 'SETUP: AUTOTEST TYPE' screen will display.

Use the UP/DOWN arrow keys to highlight the type of test required. Then press ENTER to select.

4. 'SETUP: AUTOTEST WAVE' screen will display. There are seven wavelength options listed on two menu screens to select from.

Screen 1 of 2: 1310/1550, 1490/1550, 1310/1490/1550nm.

Screen 2 of 2: 1310nm, 1490, 1550 and 1310/1490nm



Use the UP/DOWN arrow keys to highlight the wavelength(s) and scroll between choices. Then press ENTER to select.

Press Back-arrow softkey to return to the previous screen

or 1/2, 2/2 Press softkey to toggle between AutoTestWave screens.

Setup Functions Continued. . .



5. 'SETUP: AUTOSAVE' screen will display. Use the UP/DOWN arrow softkeys to highlight NO or YES indicating whether you want to Autosave test results. Then press ENTER to select.


Note: If NO is selected, you will have another opportunity to save your test measurements for later recall.

6. 'SETUP: THRESHOLD' screen will display. Use the UP/DOWN arrow softkeys to highlight NO or YES, indicating whether you want to set Threshold levels for your test results. Then press ENTER to select.



Note: Thresholds are used to set and display Pass/Fail levels in test reporting.

If No is selected, a Pass/Fail result will not be provided with the test results and the display will return to the AutoTest screen.



7. Another 'SETUP: THRESHOLD' screen will display. Use the LEFT/RIGHT keys to highlight the digit to be set in each box. Use the UP/DOWN keys to change the numbers. Press the Enter button to select, and move to the next line. Repeat the same steps for all frequencies if required.

When complete, press the SAVE softkey to return to the Autotest screen.

QUICK START GUIDE *Continued. . .*


REMEMBER: To ensure absolute measurement accuracy, fiber optic connectors must always be cleaned before conducting a fiber optic measurement.

Establish Measurement Reference

1. At the AutoTest Main Screen establish a reference using the SIDE-BY-SIDE or LOOPBACK method by pressing the REF softkey and performing the following:




2A. Side-by-Side Reference -



Note: The unit initiating a test or reference is the 'Master' or 'Local' unit, and will display the references. The other unit is the 'Slave' or 'Remote'. For side-by-side reference, leave the Remote unit in the Startup screen.


- a. Use the UP/DOWN arrow keys to highlight SIDE BY SIDE.
- b. Press ENTER button to select.
- c. Per the screen diagram, connect Patch Cables to both units at the Source/Tx Ports.
- d. Press the NEXT softkey to continue. (While referencing, the master unit will indicate 'Referencing' and the slave will display 'Measuring'.)



- e. When complete, a checkmark will appear on the Master Unit screen and 'Referencing Completed' will be indicated on the 'Slave' unit. Press DONE on the Master unit, and EXIT on the Slave to return to the AutoTest Screen.
- f. Go to Step 4.

Establish Measurement Reference *Continued...*

3B. Loopback Reference –



Perform these steps on both Master and Slave units:

- a. From AutoTest Screen press the REF softkey.
- b. Use the UP/DOWN arrow keys to highlight LOOP BACK.
- c. Press ENTER button to select.



- d. Per the screen diagram, connect the Reference Cable from the Source Rx to the Source Tx Port.
- e. Press the NEXT softkey to continue.
- f. When complete, a checkmark will appear on screen. Press DONE softkey to return to the AutoTest Screen.

4. Disconnect reference cables from the Rx port(s) or each other (if Side by Side was used).

Note: If referencing errors occur -

- Check Connections.
- You can redo reference or exit to use old reference.

5. Leave the fiber connected to the Tx Port.

Note: Disconnection of this cable will cause loss of references.

You are now ready to perform an AutoTest.

QUICK START GUIDE *Continued. . .*

Running an IL/RL AutoTest – 1310/1490/1550

1. At the AutoTest Main Screen, for record purposes, use the Arrow buttons and Enter key to identify Cable and Fiber names.


Use the LEFT/RIGHT keys to highlight the digit to be set.

Use the UP/DOWN keys to change the numbers.

Press the Enter button to select, and move to the next line.



2. To begin the AutoTest sequence, press the AutoTest button on the unit. **NOTE:** The unit that initiates the test becomes the Master or Local. The other becomes the Slave or Remote.



3. The Master unit display will indicate the connections to be made.

Clean all interfaces and connect the reference cables still attached to the Source/Tx Port from each test unit to the Fiber to be tested.

4. Press the AutoTest button on the Master unit again to begin testing. Both units will indicate 'Measuring'.



5. When testing completes the unit will display measurement test results.

NOTE: If you did *not* select AutoSave during Setup, you have the option to press the SAVE softkey and follow the screen instructions to save the measurement results.

Running an IL/RL AutoTest – Continued...

EXAMPLE OF MEASUREMENT TEST RESULTS:

Measurement test results will be displayed on up to five screens as follows:

SCREEN 1 -

C:\Cable000		F:003	
	ILavg	RLavg	
1310	Pass	Pass	
1490	Pass	Pass	
1550	Pass	Pass	
MORE			REDO

1. Screen 1 indicates IL & RL (A to B & B to A) Pass/Fail averages for each wavelength measured. Pass/Fail results appears only if *all* Threshold settings have been input. If not, Screen 2 will be displayed.

Press the MORE softkey to review additional test results *or* Press Redo to repeat AutoTest.

SCREEN 2 -

C:\Cable000		F:003	
	ILavg	RLavg	
1310	-0.01	56.8	
1490	1.61	60.6	
1550	0.00	62.7	
MORE			REDO

2. Screen 2 displays IL & RL (A to B & B to A) averages for each wavelength measured.

Press the MORE softkey to repeat the test result again *or* Press Redo to repeat AutoTest.

SCREEN 3, 4, 5 -

C:\Cable000		F:003	
1310	IL	RL	
A-B	0.00	56.2	
B-A	-0.02	57.3	
Mar	2.99	21.8	
λ			←

3. Screens 3, 4 and 5 display the individual IL & RL results for each wavelength measured.

Press the lambda softkey to scroll through the individual measurement results for each wavelength.

Press the Back-arrow softkey to return to Screen 2.

Continued. . .

Running an IL/RL AutoTest – Continued...

TO CONTINUE TESTING ADDITIONAL FIBERS -

1. Press the AutoTest button to return to the AutoTest screen. If the previous test was saved, the fiber number will automatically sequence up. (i.e. Fiber 001 changes to 002)
2. To begin the AutoTest sequence, press the AutoTest button on the unit.
3. The screen will indicate the connections to be made.
4. Clean all interfaces and connect the reference cables to the Fiber under test.
5. Press the AutoTest button on the Master unit again to begin testing.

NOTE:

IF AUTOTEST FAILS to COMPLETE -

1. Check all connections for correctness and cleanliness.
2. Ensure Link Loss is <40dB at 1310/1490/1550nm.
3. Keep Remote unit in Startup screen (IL 1310/1490/1550).
4. Ensure reference step has been completed.



AUTOTEST MAIN SCREEN

At powerup, the splash screen will briefly display the 525's firmware version and model number, and then display the Autotest Main Screen.

From the Autotest Main Screen, Insertion Loss Return Loss testing can be performed at 1310, 1490 & 1550nm. Cable and Fiber names can be designated for record management of stored measurements and later recall.

Changing Designations - Use the LEFT/RIGHT arrow keys to move the highlighted screen cursor to the cable designation field to be set. Use the UP/DOWN arrow keys to scroll thru alphanumeric entries for cable designations.

When designated, press the ENTER button to set the Cable name and move the to the Fiber field. Use the LEFT/RIGHT arrow keys to move the highlighted screen cursor to the Fiber designation field to be set. Use the UP/DOWN arrow keys to scroll thru numeric entries for fiber designations. Press the ENTER button to set the entry.

Auto Increment Feature - The numeric Fiber designations will automatically sequence up when successive testing is performed, if Autosave is turned on.

REF - Softkey accesses the Reference Methods screen to establish either a Side-by-Side or Loopback reference for testing. (See pg. 22)

SETUP - Softkey accesses Setup screen to configure the 525 for type of test(s), wavelength(s), Auto file save, threshold settings (See pg. 23)

MENU - Softkey accesses the Menu screen to View Data from previously stored tests, open the Tools display, and open the Optical Power Meter and Power Source screen and access the Return Loss Meter. (See pg. 26)



REFERENCE METHOD SCREENS



From the Autotest Main screen, press the REF softkey. The Reference Method screen will be displayed. Use the UP/DOWN arrow keys to highlight SIDE BY SIDE or LOOP BACK.

Press the Enter button to select the method.

SIDE-BY-SIDE METHOD:

- a. Per the screen diagram, connect the Reference Cable from the Source/Return Loss Port of the Master Unit to the Source/Return Loss Port of the Slave Unit.
- b. Press the NEXT softkey to continue.
- c. When complete, a checkmark will appear on screen.
- d. Press DONE softkey to return to the AutoTest Screen.




LOOPBACK METHOD:

- a. Per the screen diagram, connect the Reference Cable from the Source/Return Loss Port to the Power Meter Port.
- b. Press the NEXT softkey to continue.
- c. When complete, a checkmark will appear on screen.
- d. Press DONE softkey to return to the AutoTest Screen



SETUP SCREENS



From the Autotest Main screen, press the SETUP softkey. The Setup : AutoTest Type screen will be displayed. The user can select through the following setup options:

SETUP: AUTO TEST TYPE -

Use the UP/DOWN keys to highlight the type of Autotest to run -

IL - Insertion Loss

RL - Return Loss

IL/RL - Insertion Loss and Return Loss

Press ENTER to select and move to Setup: AutoTest Wave screen.

Press Cancel to return to the AutoTest screen.



SETUP: AUTO TEST WAVE -

Use the UP/DOWN keys to highlight the wave-length(s) to measure during AutoTest -

Screen 1 of 2: 1310/1550, 1490/1550,
1310/1490/1550nm.

Screen 2 of 2: 1310nm, 1490, 1550
and 1310/1490nm

Press ENTER to select and move to Setup: Autosave.

Press the Back-arrow softkey to return to the previous screen.

Press the **1/2**, **2/2** softkey to toggle between AutoTestWave screens.

Press Cancel to return to the AutoTest screen.

SETUP SCREENS *Continued...*



SETUP: AUTOsave

The 525 can store and recall more than 1000 test measurements. Use the UP/DOWN arrow softkeys to highlight NO or YES indicating whether you want to automatically save test results.

Press ENTER to select.

Press the Back-arrow softkey to return to the previous screen.

Press Cancel to return to the AutoTest screen.

Note: If NO is selected during Setup, you will have another opportunity to save your test measurements for later recall.



SETUP: THRESHOLD (1st Screen)

Thresholds are used to set and display Pass/Fail levels in test reporting. Use the UP/DOWN arrow softkeys to highlight NO or YES indicating whether you want to set Threshold values.

Press ENTER to select.

Press the Back-arrow softkey to return to the previous screen.

Press Cancel to return to the AutoTest screen.

If No is selected, thresholds values will not be used and a Pass/Fail result will not be provided with the test results.

SETUP SCREENS *Continued...*

SETUP: THRESHOLD		
	IL	RL
1310	03.0	35.0
1490	03.0	35.0
1550	03.0	35.0

← SAVE

SETUP: THRESHOLD (2nd Screen)

To set Insertion and Return Loss threshold values for each wavelength, use the LEFT/RIGHT keys to highlight the digit to be set in each box.

Use the UP/DOWN keys to change the numbers.

Press the Enter button to select, and move to the next line.

Repeat the same steps for all wavelengths required.

When complete, press the SAVE softkey to return to the Autotest screen.

MENU SCREEN



From the Autotest main screen, press the MENU softkey. The MENU screen will be displayed.

Use the UP/DOWN arrow keys to highlight the function to perform, then press the Enter button to select.

The following functions are available -

VIEW DATA - Access and view up to 1000 test measurements stored in memory. (Go to pg. 27)

TOOLS - Access and modify the following:

SET DATE/TIME - Manually set the 24 hour clock & calendar of the 525. (Go to pg. 29)

ZERO - Zero out the Optical Power Meter & obtain a noise level baseline. (Go to pg. 30)

AUTO OFF - Enable / Disable the 15 minute automatic shut off feature. The 525 default is - On. (Go to pg. 30)


OPM / SOURCE - Perform Optical Power Meter measurements and turn the Laser source on & off. (Go to pg. 31)

RETURN LOSS- Access the Return Loss meter at 1310nm, 1490 and 1550nm. (Go to pg. 33)

EXIT - Press the Exit softkey to return to the Autotest Screen.

NOTE: LCD CONTRAST CONTROL - The 'Backlight' key can be used in this screen for LCD contrast control. Hold down the backlight button for 5 seconds or more to cycle between maximum and minimum LCD contrast. Release key at desired contrast level.

VIEW DATA SCREENS



VIEW DATA

From the Menu screen, use the UP/DOWN arrow keys to highlight the View Data function, then press the Enter button to select. The stored test results menu will be displayed (by Cable & Fiber). The latest result is always on top.

You can access and view more than 1000 test measurements stored in memory.

Use the UP/DOWN arrow keys to highlight the test to be recalled. Press the Enter key to display the first test results screen as follows -

The screenshot shows a table with the following data:

	ILavg	RLavg
1310	Pass	Pass
1490	Pass	Pass
1550	Pass	Pass

At the bottom of the screen, there are two softkeys: 'MORE' and 'REDO'.

All wavelengths from the selected AUTOTEST are displayed. The PASS/FAIL indicator is based on the threshold set for that particular wavelength. If the average measurement value is less than the threshold, PASS is indicated. If the average measurement is greater than the threshold, FAIL is indicated. This screen only appears if the user input all threshold settings, if not, Screen 2 is displayed

Press MORE softkey to review additional test results for this fiber

Press DEL softkey to delete the stored test result.

Press EXIT softkey to return to the VIEW DATA Screen

Continued . . .

VIEW DATA SCREENS *Continued . . .*

	ILavg	RLavg
1310	-0.01	56.8
1490	1.61	60.6
1550	0.00	62.7

MORE REDO

Screen 2 displays IL & RL averages for each wavelength measured. Average is the sum of (A to B) and (B to A) divided by 2 for that particular wavelength

Press MORE softkey to review additional test results for this fiber

Press DEL softkey to delete the stored test result.

Press EXIT softkey to return to the VIEW DATA Screen

1310	IL	RL
A-B	0.00	56.2
B-A	-0.02	57.3
Max	2.99	21.8

λ ←

Screens 3, (and 4 & 5 if required) display by screen the individual Insertion and Return Loss results for each wavelength measured.

Press the lambda softkey to scroll through the individual measurement results for each wavelength.

Press DEL softkey to delete the stored test result.

Press the Back-arrow softkey to return to Screen 2 (IL & RL averages).

TOOLS SCREENS



TOOLS

From the Menu screen, use the UP/DOWN arrow keys to highlight the TOOLS function, then press the ENTER button to select. Use the UP/DOWN arrow keys to highlight the function, then press the ENTER button to select. To access and modify the following:

SET DATE/TIME - Manually set the 24 hour clock & calendar of the 525. (See below)

ZERO - Zero out the Optical Power Meter & obtain a noise level baseline. (Go to pg. 30)

AUTO OFF - Enable / Disable the 15 minute automatic shut off feature. The 525 default is - On. (Go to pg. 30)



SET DATE/TIME

From the Tools screen, use the Up/Down arrow keys to highlight the SET DATE/TIME function, then press the ENTER button to select. The SET DATE/TIME screen will be displayed.

Use the arrow keys to highlight the Date - MM/DD/YY and Day to be changed. Then use the ENTER button to move to the next line.

Use the arrow keys to highlight the 24 Hour clock Time - HH:MM:SS to be changed. Then use the ENTER button to Set.

Press the EXIT softkey to return to the TOOLS Screen.

TOOLS SCREENS *Continued . . .*



ZERO

To Zero the Optical Power Meter and obtain a noise level baseline, do the following:

From the Tools screen, use the UP/DOWN arrow keys to highlight the ZERO function, then press the ENTER button to select.

The screen will instruct you to place the Black Cap on both of the ports.

Press the ZERO softkey.

When the unit has zeroed the display will automatically return to the Tools screen.

Note: An Error message will appear if the ports are not capped properly or if cap is not black.



AUTO OFF

Enables or Disables the 15 minute automatic shut off feature.

From the TOOLS screen, use the UP/DOWN arrow keys to highlight the AUTO OFF function, then press the Enter button to select.



At the Auto Off screen, select:

Yes - to activate the automatic 15 minute shut off

No - to deactivate the automatic 15 minute shut off

The default setting is - Yes.

OPM / SOURCE



To perform Optical Power Meter measurements and turn the Laser Source on & off, do the following:

From the MENU screen, use the UP/DOWN arrow keys to highlight OPM / SOURCE then press the ENTER button to select.

The POWERMETER/SOURCE screen will be displayed.

1. Use the arrow buttons and the ENTER key to highlight & set the following OPTIONS -

Top row boxes from left to right:

SET MEASUREMENT WAVELENGTH -

Use the UP/DOWN buttons to toggle the test wavelength, displayed in the left hand box, to either - 1310nm, 1490 or 1550nm.

TURN SOURCE ON OR OFF - Use the Right arrow button to highlight the SRC ON/SRC OFF box. Use the Up/Down & Enter buttons to toggle SRC ON or OFF.

SET THE POWER MEASUREMENT

UNITS - Use the Right arrow button to highlight the POWER UNIT

SELECTION box. Use the UP/DOWN & ENTER buttons to toggle between:

dBm - absolute power / logarithmic scale

Watts - absolute power / linear scale

Rel - relative power / reference mode

Continued . . .

OPM / SOURCE *Continued . . .*



AUTORANGE / HOLD- Use the Right arrow button to highlight the AUTO/HOLD box.

When Measuring in Watts, use the UP/DOWN & ENTER buttons to toggle between:

AutoRange - unit will seek the power range required to perform the test.

Hold - Unit will lock-in the power range currently set.

Note: HI or Lo will be displayed if input power is beyond the capability in the range currently held.


2. The power measurement will be displayed on the screen.
3. To save the reading, press the SAVE softkey. The screen will prompt you to identify the Cable & Fiber.
4. Use the Arrow buttons and Enter key to identify the Cable name and Fiber number,
5. Press SAVE softkey. The unit will return to the POWERMETER/SOURCE screen to perform additional testing if required.

REF To set a new 0dB reference level, connect the fiber to the unit and hold the REF softkey. The unit will automatically zero out. Release the key.

SAVE To save an optical power reading, press the SAVE softkey while the reading is displayed. The screen will prompt for Cable Name and Fiber Number.

MENU To return to the Menu Screen, press the MENU softkey.

RETURN LOSS




To perform Return Loss measurements and turn the Laser Source on & off, do the following:

From the MENU screen, use the UP/DOWN arrow keys to highlight **RETURN LOSS** , then press the ENTER button to select.

The RETURN LOSS METER screen will be displayed.

1. *Clean all optical interfaces* (see pg. 11) and attach the reference cable to the Source/Return Loss Port.
2. Establish a reference by pressing the REF softkey.
3. Per the on-screen diagram, wrap the Reference Cable around a mandrel 7 times and press the NEXT softkey to continue.
4. When the screen indicates UN-WRAP, remove and straighten the fiber and press the NEXT softkey.
5. The screen will return to the RETURN LOSS METER. Connect the Reference Cable to the fiber or device under test.
6. Use the Up/Down buttons to toggle the test wavelength, displayed in the highlighted left hand box, to either 1310nm, 1490nm, or 1550nm.
7. The Return Loss measurement will be displayed.

RETURN LOSS *Continued . . .*



8. To store the test, press the SAVE soft-key. The screen will prompt you to identify the Cable & Fiber.
9. Use the Arrow buttons and Enter key to identify the Cable name and Fiber Number.
10. Press SAVE softkey. The unit will return to the RETURN LOSS Meter screen to perform additional testing if required.



Specifications

Optical Power Meter Specifications

Power Measurement Range in dBm Wavelength \geq 850 - 1700nm	+10dBm to -65dBm
Wavelength Range	800nm to 1700nm
Calibration Points	850nm, 980nm, 1490nm, 1310nm, 1550nm, 1625nm
Absolute Accuracy 1310nm with -10dBm input power	$\leq \pm 0.25$ dB (6%)
Linearity @ 1310nm Linearity Accuracy	
+10 to -3dBm	± 0.22 dB
-3 to -55dBm	± 0.05 dB
-55 to -65dBm	± 0.22 dB
Optical stability OPM Channel only ¹	$\leq \pm 0.05$ dB (0°C - 50°C $\pm 1^\circ\text{C}$ 24hr@ >-30 dBm) ¹
Settling time, auto-range	0.5 second (typical)
Optical Power Measurements	dBm, dB, Watt
Polarization Dependency	≤ 0.10 dB
Mating Stability of SOC Connector	≤ 0.02 dB
Repeatability	≤ 0.05 dB
Optical Interface Power Meter Optical Interface MM Laser Power Source	SOC Adapter UCI-APC (angle polished) Adapter, 9/100 SM

1. While temperature is running profile from 0°C to +50°C

Specification Summary of Lasers

Central Wavelength	1310nm±30nm	1490nm±30nm	1550nm±30nm
Spectral Bandwidth	<5nm	<5nm	<5nm
Stability			
Variation of ≤ ±10°C from +17 to +40 ²	≤ ±0.25dB	≤ ±0.25dB	≤ ±0.25dB
Variation from 25°C from +0 to +50 ²	≤ ±0.75dB	≤ ±0.75dB	≤ ±0.75dB
Power Output¹			
Typical (factory adjusted)	>-4dBm±1.0dB	>-7dBm±1.0dB	>-7dBm±1.0dB
Mating Stability of Connector	< 0.2dB	< 0.2dB	< 0.2dB
Connector Interface	Universal Connector Interface (UCI-APC)		

1. Within specified ambient environment of +20°C to +25°C
2. Instrument is ramped up from 0°C to +50°C in 5°C steps/30 min. The instrument is allowed to stabilize at each of these temperatures for 30 minutes. Initial reference power level is measured at approximately +25°C.

AutoTest Specifications

Wavelength	1310/1490/1550nm
Measurement Mode	Bi-directional Simplex
Measurement Range	>40dB

Return Loss Specifications

Return Loss Accuracy	
UCI-APC	10 to 45dB < ±0.5dB (Best case for Conn. type) 10 to 40dB < ±0.5dB (AutoTest)
Measurement Range	>40dB

Mechanical Specifications

Dimensions	
Enclosure	6.50" x 1.75" x 3.90"
Rubber Boot	7.60" x 4.30" x 2.30"
Accessories	Soft shock-proof boot, Tilt Up Stand, NIMH Battery Pack
Weight w/batteries & boot	2.20 lbs.

Parts and Accessories

To order accessories, SOC adapters, and parts, contact your local Tempo distributor.

Accessories

Description

RS232 interface cable kit
Printer serial cable kit
Nickel-metal hydride battery pack
Power transformer/NiMH charger

Cleaning Supplies

Description

All-In-One connector cleaner
Adapter cleaning wands
200X Leica FiberVue microscope

SOC Adapters

Snap-On Connector (SOC) adapters are available for a broad range of fiber optic connector types. Order additional adapters by specifying the codes listed below.

<u>Adapter Code</u>	<u>Connector Type</u>
1001	Blank
1010	DIN 47256
1020	SOC ADAPTER, FC
1030	SOC ADAPTER, ST
1038	MIL-T-29504 optical termini
1040	HMS-10 (2.5mm)
1047	Mini-BNC
1050	Diamond HMS-0 (3.5mm)
1057	Stratos 430/Holtek 38000
1062	SOC ADAPTER, SC
1081	Radiall VFO
1086	Diamond HMS-10A (SMA-2.5)
1087	SMA-905/906
10E0	Radiall EC
10E2	Diamond E-2000
10TB	Simplex TOSLINK/Spectran J-pin
10TD	TR/TX set, duplex TOSLINK/Spectran J-pin
10TR	Duplex TOSLINK TX
10TX	Duplex TOSLINK TR
10ZP	H-P Versalink/Spectran V/Z-pin

UCI Adapters

Universal Connector Interface (UCI) adapters are available for most industry standard fiber optic connector types. Order additional adapters by specifying the codes listed below.

<u>Adapter Code</u>	<u>Connector Type</u>
AE2-10	Diamond E-2000
APC-108/C	Ceramic UCI, FC
AMS-00	Diamond HMS-0 (3.5mm)
AMT-10	Diamond HMS-10A (SMA-2.5)
ASM-90	SMA-905/906
AHP-10	HMS-10/HP (2.5mm)
AML-38	MIL-T-29504/4 and /5
ASC-108/C	Ceramic UCI, SC
ATS-108/C	Ceramic UCI, ST

Technical Support and Service

Tempo offers free technical support for the 525 optical test sets. If you have questions or comments about your instrument, call Tempo Monday through Friday, from 8 a.m. to 5 p.m. Pacific time.

Please have the following information available:

1. Instrument model number
2. Instrument serial number
3. Description of the problem

To obtain service for the instrument, call the toll-free number noted on the back cover, or contact your local Tempo representative.

Periodic Calibration

It is recommended that the 525 optical test set be recertified and/or recalibrated every 24 months, or by the due date printed on the calibration decal affixed to the instrument, whichever comes first. Calibration of the instrument may be performed by Tempo for a nominal fee. Please call Tempo during business hours for more information.



Tempo[®]
A Telextron Company



1390 Aspen Way 6 Vista, CA 92081
760-598-8900 6 800-642-2155 6 Fax 760-598-5634
M – F 6 7:00 a.m. – 4:30 p.m. 6 Pacific Time

Unit 3, Maesglas Industrial Estate
Newport, NP20 2NN, UK
+44 (0) 1633 223552 • Fax +44 (0) 1633 223948

www.tempo.textron.com